03/21/2	2013 04:26pm	BRIDGEATROCKWOA	865354	2737	#850	Page 15	/17
CEM11	<u>ERO FOR MEDICARI</u>	AND HUMAN SERVICES	45	X	4/13/13	PRINTED	: 02/28/2013 APPROVED
IOIAIEMEI	NT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MI A. BUII		CONSTRUCTION 01 - MAIN BUILDING 01	(X3) DATE S	. 0938-0391 URVEY ETEO
		445143	B. WIN	Ġ			
NAME OF PROVIDER OR SUPPLIER			╼┶╌╷	STREET ADDRESS, CITY, STATE, ZIP CODE		5/2013	
BRIDGE AT ROCKWOOD, THE				5580	ROANE STATE HWY KWOOD, TN 37854		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREFIX TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU GROSS-REFERENCED TO THE APPRI DEFICIENCY)	II C BE	(X6) COMPLETION DATE
K 029	One hour fire rated fire-rated doors) or extinguishing system and/or 19.3.5.4 profit the approved automoption is used, the approved automoption is used, the approved automoption is used, the approved protect 48 inches from the inches from	not met as evidenced by: on, it was determined that the re that doors to hazardous tuary 25, 2013 at 2:25 p.m, ed that the following to hazardous areas propped ding into the dining room was chair, our door was held open by a	Ko	Re Alli this on Syys SD doc Any corr Adı Mo Any and	FPA 101 Life Safety Code Standar 1029 ne hour fire rated construction (with ted doors) or an approved automatic stringuishing system in accordance with different fire extinguishing system in accordance with different fire extinguishing string is used, the areas are separated faces by smoke resisting partitions and sors are self-closing and non-rated or plied protective plates that do not excepts from the bottom of the door are plied protective plates that do not excepts from the bottom of the door are plied protective. Staff were immediated residents have the potential to be affected practice. Staff were immediated and propping doors open. Stemic measures: C or designed will educate staff on most open. Rounds will be conducted a pughout the work week by department of the doors propped open will be immediated and staff educated, and reported ministrator during stand down meeting itoring measures: c concerns will be reported to the Adaptive for the conduction of the co	A hour fire- fire th 8.4.1 s. When the system from other if doors, field- seed 48 secunitted, li fected by ely educated of propping laily t heads, ately d to the g.	
SS=D	director and acknowl during the exit confer NFPA 101 LIFE SAF Cooking facilities are	verified by the maintenance edged by the administrator ence on February 25, 2013. ETY CODE STANDARD protected in accordance	K 069	9			
BORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE							
Melin farti Administrator 3/21/13							
y deficiency statement enging with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that							

Any deficiency statement enting with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is regulate to continued

FORM CMS-2587(02-99) Previous Versions Obsolele

Event ID: \$LIF21

Facility ID: TN7302

If continuation sheet Page 1 of 2

DEPARTMENT OF HEALTH AND HUMAN SERVICES PRINTED: 02/28/2013 CENTERS FOR MEDICARE & MEDICAID SERVICES **FORM APPROVED** STATEMENT OF DEFICIENCIES <u>OMB NO. 0938-0391</u> (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION (X3) DATE SURVEY IDENTIFICATION NUMBER: A. BUILDING COMPLETED 01 - MAIN BUILDING 01 B. WING 445143 NAME OF PROVIDER OR SUPPLIER 02/25/2013 STREET ADDRESS, CITY, STATE, ZIP CODE BRIDGE AT ROCKWOOD, THE 5580 ROANE STATE HWY ROCKWOOD, TN 37854 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL (X5) COMPLETION PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) K 069 Continued From page 1 K069 K 069 Cooking facilities are protected in accordance with with 9.2.3, 19.3.2.6, NFPA 96 Residents affected/potentially affected; This STANDARD is not met as evidenced by: All residents have the potential to be affected by Based on observation, it was determined the this cited practice. The two basket deep fryer was facility failed to have an approved extinguishing removed from the concession area and taken out of agent over cooking appliances. service. Systemic measures: The findings include: After removal of deep fryer, a quote was obtained for the required extinguishing agent. SDC/designee Observation on February 25, 2013 at 2:21 p.m. educated staff on the removal of the deep fryer from revealed that Archie's Concession area was using the concession area. Plant Ops director was made a two (2) basket deep fryer with no extinguishing aware that the fryer could not be utilized without the presence of the appropriate extinguishing agent agent installed for this cooking appliance. in place. Monitoring measures: This finding was verified by the maintenance Plant Ops director/designee will check the director and acknowledged by the administrator concession area throughout the week to ensure that during the exit conference on February 25, 2013. no fiver is in place or being utilized. Any concerns will be corrected immediately and be reported to the Administrator.